STATE OF COL

John W. Hickenlooper, Governor Larry Wolk, MD, MSPH Executive Director and Chief Medical Officer

Dedicated to protecting and improving the health and environment of the people of Colorado

Laboratory Services Division

4300 Cherry Creek Dr. S. Denver, Colorado 80246-1530

8100 Lowry Blvd. Denver, Colorado 80230-6928 Phone (303) 692-2000

(303) 692-3090 Located in Glendale, Colorado

www.colorado.gov/cdphe



APPROVED LIST OF BREATH ALCOHOL IGNITION INTERLOCK DEVICES (BAIID's)

Pursuant to Colorado Revised Statutes section 42-2-132.5 (7)(a), effective January 1, 2001:

For the purposes of this section, "approved ignition interlock device" means a device approved by the department of public health and environment that is installed in a motor vehicle and that measures the breath alcohol content of the driver before a vehicle is started and that periodically requires additional breath samples during vehicle operation. The device may not allow a motor vehicle to be started or to continue normal operation if the device measures an alcohol level above the level established by the Department of Public Health and Environment.

And pursuant to the Rules and Regulations of the Colorado State Board of Health, Ignition Interlock Devices 5 CCR 1005-3 Section 1.1:

Statement of Basis and Purpose: The following rules and regulations shall govern the approval of ignition interlock devices, also known as breath alcohol ignition interlock devices, and shall establish the setpoint breath alcohol concentration at which the device will prevent a motor vehicle from starting.

TO: Whom It May Concern

FROM: Colorado Department Of Health And The Environment.

Certification Program Laboratory Services Division

September 17, 2013 DATE:

Approved List of BREATH ALCOHOL IGNITION INTERLOCK DEVICES (BAIID) SUBJECT:

| Manufacturer | Device/Model | Notes |
|------------------------------------|----------------------|--------------------------------|
| Intoxalock | Intoxalock | Subsidiary of Combined Systems |
| 10520 Hickman Road Suite F | | Technology |
| Des Moines, IA 50325 | | |
| 877-777-5020 | | |
| www.intoxalock.com | | |
| National Draeger, Inc. | Model XT | |
| Breathalyzer Division | | |
| 4040 W. Royal Ln Suite 136 | | |
| Irving, TX 75063 | | |
| 972-929-1100 | | |
| 866-385-5900 | | |
| www.draeger.com | | |
| Guardian Interlock Systems | Model AMS 2000 | Local office: 5475 Peoria |
| 110 Marietta Station Walk | | Denver, CO 80239 |
| Marietta, GA 30060 | | |
| 770-499-0499 | | |
| www.guardianinterlock.com | | |
| LifeSafer Interlock, Inc | FC-100 | National Interlock is sibling |
| 4290 Glendale Milford Road | SC-100 | company |
| Cincinnati, Ohio 45242-3704 | | |
| 800-475-5490 | | |
| www.lifesafer.com | | |
| Smart Start, Inc. | Smart Start | |
| 4850 Plaza Drive | Model SSI-1000 | |
| Irving, TX 75063 | Model SSI 20/20 | |
| 800-880-3394 | Model SSI 20/30 | |
| | | |
| Alcohol Sensors International, LTD | Sens-O-Lock FR-9000 | Sens-O-Lock of America |
| 90 13 th Avenue | | 39 Mohawk Trail |
| Ronkonkoma, NY 11779 | | Slingerlands, NY 12159-9433 |
| 718-828-9660 | | 404-748-4484 |
| www.sensolockamerica.com | | |
| Auto Sense International, Inc. | ALCO-LOCK Series III | |
| 683 East Brokaw Road | | |
| San Jose, CA 95112 | | |
| 408-325-2357 | | |
| www.autosenseintl.com | | |
| Interceptor Ignition Interlock | Interceptor Ignition | |
| 26 Moriches Ave. | Interlock Model M-1 | |
| Mastic, NY. 11950 | | |